



Dimensions for screws and bolts

Note: When inquiring about 5 digit part numbers beginning with 8, please preface the number with R264-. Example: 88111 should be R264-88111.

Chipboard screws

R264 - article	Dimensions	3	3.5	4
88095	d_k	6	7	8
	k_{min}	1.8	2.1	2.4
	d_2	1.9	2.5	2.67
	cross recess size	1	2	2

R264 - article	Dimensions	3	3.5	4	4.5	5	6
88096	d_2	1.9	2.5	2.67	2.7	3	3.7
	d_k	6	7	8	9	10	12
	k_{1max}	2.25	2.6	2.8	3	3.5	4.1
	y	3	3.4	4	4.3	4.8	5.7
	cross recess size	1	2	2	2	2	3

R264 - article	Dimensions	3	3.5	4	4.5	5	6
88097	d_2	1.9	2.5	2.67	2.7	3	3.7
	d_k	6	7	8	9	10	12
	k_{1max}	1.9	2.1	2.5	2.7	3	3.6
	k_{2max}	1.6	1.8	2	2.2	2.5	3
	y	3	3.4	4	4.3	4.8	5.7
	cross recess size	1	2	2	2	2	3

R264 - article	Dimensions	3	3.5	4	4.5	5	6	8
88098	d_2	1.9	2.5	2.67	2.7	3	3.7	5
	d_k	6	7	8	9	10	12	15.1
	k_{1max}	1.9	2.1	2.5	2.7	3	3.6	4.4
	k_{2max}	1.6	1.8	2	2.2	2.5	3	3.7
	y	3	3.4	4	4.3	4.8	5.7	6.5
	TORX size	T10	T15	T20	T20	T25	T30	T40

Hooks/special bolts with wood screw thread

R264 - article	Dimensions	6 x 3	8 x 3	8 x 4	10 x 3	10 x 4	10 x 6	12 x 3	12 x 4	
88133	w	3	8	4	3	4	6	3	4	
	d	2	2	2.3	2	2.3	2.9	2.0	2.3	
	l	6	8	8	10	10	10	12	12	
	l_1	4	5	5	7	7	7	8	8	
	Dimensions	12 x 6	12 x 8	12 x 10	16 x 4	16 x 6	16 x 8	16 x 10	16 x 12	
	w	6	8	10	4	6	8	10	12	
	d	2.9	3.3	3.7	2.3	2.9	3.3	3.7	3.9	
	l	12	12	12	16	16	16	16	16	
	l_1	8	8	8	10	10	10	10	10	
	Dimensions	20 x 6	20 x 8	20 x 10	20 x 12	25 x 8	25 x 10	25 x 12	25 x 14	
	w	6	8	10	12	8	10	12	14	
	d	2.9	3.3	3.7	3.9	3.3	3.7	3.7	4.0	
	l	20	20	20	20	25	25	25	25	
	l_1	12	12	12	12	15	15	15	15	
	Dimensions	25 x 16	30 x 8	30 x 10	30 x 12	30 x 14	30 x 16	30 x 18	40 x 12	
	w	16	8	10	12	14	16	18	12	
	d	4.6	3.3	3.7	3.9	4.0	4.6	5.0	3.9	
	l	25	30	30	30	30	30	30	40	
	l_1	15	18	18	18	20	18	18	22	
	Dimensions	40 x 14	40 x 16	40 x 18	40 x 20	50 x 14	50 x 16	50 x 18	50 x 20	
	w	14	16	18	20	4	16	18	20	
	d	4.0	4.6	5.0	5.2	4.0	4.6	5.0	5.2	
	l	40	40	40	40	50	50	50	50	
	l_1	25	22	22	22	25	25	25	25	

screw eyes
type 1